

**From:** [Moore, Gary](#)  
**To:** [Crossland, Ronnie](#)  
**Cc:** [Todd, Brandi](#); [Webster, Susan](#)  
**Subject:** CES Spill  
**Date:** Friday, August 01, 2014 10:56:04 PM  
**Attachments:** [8.1.14 CES Spill Path.jpg](#)

---

**Hello All:**

**I talked with Terry Andrews with TCEQ. The south end of the property is completely flooded. The source of the spill is still not known but speculation is that the secondary containment filled up and overflowed oily materials out of the containment and into the stormwater which exited the facility on the southwest corner on to a ROW between houses and on the Kingsbury St. It travel west down Kingsbury until it reached the storm drain.**

**The City has been on-scene since 3:00 pm today addressing the runoff and oil from the facility and have dammed it up but apparently there is staining on the roads and oily material in the dammed up area. The city has collected 6000 gallons of contaminated stormwater.**

**It is my recommendation that we should respond to the location to evaluate and determine the necessary steps. to remediate which will likely be excavation.**

**Removal and disposal of the water and possible excavation.**

**Thanks**

**Gary Moore**

**Federal On-Scene Coordinator**

**U.S. EPA Region 6**

**214-789-1627 cell**

**214-665-6609 office**

**[moore.gary@epa.gov](mailto:moore.gary@epa.gov)**